

SURVEY



Survey Number :	355	Date :	
-----------------	-----	--------	--

Survey General Information :

User	:	Assigned Date	:
Survey Template	:	Scheduled	:
Site	:	Due Date	:
Current Status	:	Arrived Date	:
	:	Closed Date	:

Survey Values

Description	:	Access	Value	:	https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\16_07_2020_13_09_385848.jpg , https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\16_07_2020_13_09_488252.jpg
-------------	---	--------	-------	---	---

Attachment :

Description :

Description	:	Site_ID	Value	:	1797
-------------	---	---------	-------	---	------

Attachment :

Description :

Description	:	Site_Type	Value	:	GF
-------------	---	-----------	-------	---	----

Attachment :

Description :

Description	:	Structure	Value	:	OK
-------------	---	-----------	-------	---	----

Attachment :

Description :

Description	:	_0_1_Date	Value	:	2020-07-16 00:00:00
-------------	---	-----------	-------	---	---------------------

Attachment :

Description :

Description	:	_0_2_Time	Value	:	1:09pm
-------------	---	-----------	-------	---	--------

Attachment :

Description :

Description : G0_5_Pictures **Value** : https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268
\\16_07_2020_13_14_098452.jpg,https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\\16_07_2020_13_14_178581.jpg,

Attachment :
Description :

Description : _0_7_Site_Pictures **Value** : https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268
\\16_07_2020_13_10_407041.jpg,

Attachment :
Description :

Description : _0_5_Access_Required **Value** : NO

Attachment :
Description :

Description : _0_6_Supervisor_Name **Value** : stanley

Attachment :
Description :

Description : Z0_1_Comments_Approval **Value** : Testing the tool

Attachment :
Description :

Description : B0_5_Anemometer_is_onsite_ **Value** : YES

Attachment :
Description :

Description : E0_5_Manual_Lifting_pictures **Value** :

Attachment :
Description :

Description : G0_1_Is_the_work_site_clean_ **Value** : YES

Attachment :
Description :

Description	: B0_10_Pictures_of_all_the_tools	Value	: https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\16_07_2020_13_12_021033.jpg,https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\16_07_2020_13_12_138102.jpg,
Attachment :			
Description :			
Description	: B0_7_Nearest_toilet_identified_	Value	: YES
Attachment :			
Description :			
Description	: E0_1_Is_a_standard_pulley_used_	Value	: NA
Attachment :			
Description :			
Description	: D0_6_Pictures_of_vehicle_on_site	Value	: https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\16_07_2020_13_13_169387.jpg,
Attachment :			
Description :			
Description	: F0_6_Mechanical_Lifting_pictures	Value	:
Attachment :			
Description :			
Description	: X0_1_Violations_Findings_on_Site	Value	: None
Attachment :			
Description :			
Description	: X0_2_Violations_Findings_Pictures	Value	:
Attachment :			
Description :			
Description	: C0_6_Electrically_qualified_person	Value	: NA
Attachment :			
Description :			

Description	:	E0_4_Is_the_drop_zone_established_	Value	:	NA
Attachment :					
Description	:				
Description	:	F0_5_Is_the_drop_zone_established_	Value	:	NA
Attachment :					
Description	:				
Description	:	E0_3_Is_enough_number_of_taglines_used	Value	:	NA
Attachment :					
Description	:				
Description	:	D0_3_Vehicle_maintenance_record_available	Value	:	YES
Attachment :					
Description	:				
Description	:	A0_1_Risk_Assessment_on_site_and_followed_	Value	:	YES
Attachment :					
Description	:				
Description	:	C0_5_Rigging_and_Slinging_certified_person	Value	:	YES
Attachment :					
Description	:				
Description	:	D0_5_Vehicle_is_fixed_with_GPS_and_Online_	Value	:	YES
Attachment :					
Description	:				
Description	:	C0_3_First_Aider_on_site_First_aid_training_	Value	:	YES
Attachment :					
Description	:				
Description	:	C0_7_Safety_Passport_pictures_Front_and_Back	Value	:	https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268 \16_07_2020_13_12_442418.jpg,
Attachment :					

Description :

Description : D0_4_Are_materials_well_kept_in_the_vehicle_ **Value** : YES

Attachment :

Description :

Description : A0_2_Method_of_statement_is_with_team_on_Site **Value** : YES

Attachment :

Description :

Description : B0_4_RF_Monitor_is_on_site_and_used_properly **Value** : YES

Attachment :

Description :

Description : B0_2_First_Aid_Box_on_site_and_properly_store **Value** : YES

Attachment :

Description :

Description : D0_2_Trained_driver_defensive_driving_training_ **Value** : YES

Attachment :

Description :

Description : G0_2_Are_materials_boxes_being_stored_properly **Value** : YES

Attachment :

Description :

Description : H0_3_PPE_Personal_Protective_Equipment_Pictures **Value** : https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\16_07_2020_13_14_338296.jpg,

Attachment :

Description :

Description : B0_6_Drinking_Water_and_disposable_cups_on_Site **Value** : YES

Attachment :

Description :

Description : C0_4_Fire_warden_on_site_Fire_fighting_training **Value** : YES

Attachment :

Description :

Description : F0_3_Crane_operator_is_equipped_with_required_PPE **Value** : NA

Attachment :

Description :

Description : B0_3_Fire_extinguisher_on_site_and_properly_stored **Value** : YES

Attachment :

Description :

Description : B0_1_Rescue_Kit_Rescuer_available_and_ready_for_use **Value** : YES

Attachment :

Description :

Description : C0_1_Site_supervisor_on_site_H_S_Supervision_Training **Value** : YES

Attachment :

Description :

Description : H0_1_PPE_Personal_Protective_Equipment_Inspections_done **Value** : YES

Attachment :

Description :

Description : B0_9_Electrical_PPEs_and_LOTO_tag_available_with_the_team **Value** : NA

Attachment :

Description :

Description : G0_4_Is_the_waste_material_area_identified_and_baricaded **Value** : YES

Attachment :

Description :

Description : E0_2_Is_a_rope_fall_arrest_system_used_to_supp **Value :** NA
ort_The_load

Attachment :

Description :

Description : C0_2_Emergency_Rescuer_Working_at_height_an **Value :** YES
d_Rescue_training_

Attachment :

Description :

Description : A0_6_Pictures_RA_Pre_task_briefing_Emergency **Value :** <https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268>
_plan_Training_TPC \16_07_2020_13_11_104921.jpg,https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/268\16_07_2020_13_11_256705.jpg,

Attachment :

Description :

Description : H0_2_PPE_Personal_Protective_Equipment_Prope **Value :** YES
rly_used_maintained_

Attachment :

Description :

Description : F0_4_Basket_is_as_per_standards_and_with_a_3r **Value :** NA
d_Party_certificate_

Attachment :

Description :

Description : D0_1_Are_Vehicles_on_site_in_good_condition_S **Value :** YES
eats_Seatbelts_Tyres_Lights_

Attachment :

Description :

Description : F0_1_Crane_and_accessories_certificates_availabl **Value :** NA
e_3rd_party_certificates_

Attachment :

Description :

Description : A0_3_PreTask_Briefing_done_correctly_and_delivered_to_all_persons_on_site_ **Value** : YES

Attachment :

Description :

Description : A0_4_Emergency_Response_Plan_ERP_on_site_and_delivered_to_all_persons_on_site_ **Value** : YES

Attachment :

Description :

Description : A0_5_All_passes_and_certificates_checked_and_activities_comply_with_trainings_ **Value** : YES

Attachment :

Description :

Description : F0_2_Crane_operator_holding_valid_driving_license_3rd_party_training_certificate **Value** : NA

Attachment :

Description :

Description : G0_3_Flammable_combustible_materials_stored_Properly_and_labeled_MSDS_Available_ **Value** : YES

Attachment :

Description :

Description : B0_8_All_tools_used_by_team_are_in_good_shape_and_Electric_connections_are_standard **Value** : YES

Attachment :

Description :