

SURVEY



Survey Number :	451	Date :	
-----------------	-----	--------	--

Survey General Information :

User	:	Assigned Date	:
Survey Template	:	Scheduled	:
Site	:	Due Date	:
Current Status	:	Arrived Date	:
	:	Closed Date	:

Survey Values

Description	:	Site_Type	Value	:	IBS
-------------	---	-----------	-------	---	-----

Attachment :

Description :

Description	:	Cable_Tray_	Value	:
-------------	---	-------------	-------	---

Attachment :

Description :

Description	:	Access_Status	Value	:	OK
-------------	---	---------------	-------	---	----

Attachment :

Description :

Description	:	Lightning_rod	Value	:
-------------	---	---------------	-------	---

Attachment :

Description :

Description	:	Busbar_Remarks	Value	:
-------------	---	----------------	-------	---

Attachment :

Description :

Description	:	Busbar_Status_	Value	:
-------------	---	----------------	-------	---

Attachment :

Description :

Description	:	Busbar_Greased_	Value	:
-------------	---	-----------------	-------	---

Attachment :

Description :

Description : Busbar_Severity **Value** :

Attachment :

Description :

Description : External_Lights **Value** : OK

Attachment :

Description :

Description : Internal_Lights **Value** : OK

Attachment :

Description :

Description : Lightning_cable **Value** :

Attachment :

Description :

Description : Site_Power_Type **Value** : kahramaa

Attachment :

Description :

Description : Cable_Tray_Cover **Value** :

Attachment :

Description :

Description : Cable_Tray_remarks **Value** :

Attachment :

Description :

Description : Grounding_Pictures **Value** :

Attachment :

Description :

Description : Cable_Tray_severity **Value** :

Attachment :

Description :

Description : Cable_Tray_Grounding

Value :

Attachment :

Description :

Description : Kahramaa_Meter_Owner

Value : Vodafone

Attachment :

Description :

Description : Main_Door_Key_Status

Value :

Attachment :

Description :

Description : Shelter_housekeeping

Value : OK

Attachment :

Description :

Description : Site_Access_Pictures

Value :

Attachment :

Description :

Description : Lightning_rod_Remarks

Value :

Attachment :

Description :

Description : Main_Contactor_Status

Value : OK

Attachment :

Description :

Description : Pole_Grounding_Status

Value :

Attachment :

Description :

Description : Busbar_Greased_Remarks **Value** :

Attachment :

Description :

Description : Kahramaa_Meter_Number_ **Value** :

Attachment :

Description :

Description : Lightning_rod_Severity **Value** :

Attachment :

Description :

Description : Main_Contactor_Remarks **Value** : abc

Attachment :

Description :

Description : Pole_Grounding_Remarks **Value** :

Attachment :

Description :

Description : Access_procedure_Status **Value** :

Attachment :

Description :

Description : Busbar_Greased_Severity **Value** :

Attachment :

Description :

Description : External_Lights_Remarks **Value** :

Attachment :

Description :

Description : Internal_Lights_Remarks **Value** :

Attachment :

Description :

Description : Lightning_cabel_Remarks

Value :

Attachment :

Description :

Description : MDB_Sub_breakers_Status

Value :

Attachment :

Description :

Description : Main_Contactor_Severity

Value :

Attachment :

Description :

Description : Pole_Grounding_Severity

Value :

Attachment :

Description :

Description : Pole_foundation_remarks

Value :

Attachment :

Description :

Description : Access_Card_Availability

Value : OK

Attachment :

Description :

Description : Cable_Tray_Cover_remarks

Value :

Attachment :

Description :

Description : External_Lights_Severity

Value : Minor

Attachment :

Description :

Description : Grounding_busbars_status **Value** : OK

Attachment :

Description :

Description : Internal_Lights_Severity **Value** : Major

Attachment :

Description :

Description : Lightning_cable_Severity **Value** :

Attachment :

Description :

Description : MDB_Sub_breakers_Remarks **Value** : abc

Attachment :

Description :

Description : Pole_foundation_severity **Value** :

Attachment :

Description :

Description : Remote_room_Location_IBS **Value** : abc

Attachment :

Description :

Description : Cable_Tray_Cover_severity **Value** :

Attachment :

Description :

Description : Grounding_Cables_labling_ **Value** :

Attachment :

Description :

Description : Grounding_busbars_Remarks **Value** : abc

Attachment :

Description :

Description : MDB_Sub_breakers_Severity

Value :

Attachment :

Description :

Description : Telecom_room_Location_IBS

Value : abc

Attachment :

Description :

Description : Earth_Pit_Grounding_Status

Value :

Attachment :

Description :

Description : Grounding_busbars_Severity

Value :

Attachment :

Description :

Description : Earth_Pit_Grounding_Remarks

Value :

Attachment :

Description :

Description : Grounding_Cables_tightened_

Value :

Attachment :

Description :

Description : Shelter_door_status_Remarks

Value : abc

Attachment :

Description :

Description : Cable_Tray_Grounding_remarks

Value :

Attachment :

Description :

Description : Earth_Pit_Grounding_Severity **Value** :

Attachment :

Description :

Description : Shelter_door_status_Severity **Value** : Crtical

Attachment :

Description :

Description : Shelter_housekeeping_Remarks **Value** : abc

Attachment :

Description :

Description : Cable_Tray_Grounding_severity **Value** :

Attachment :

Description :

Description : MDB_cables_connection_Remarks **Value** : abc

Attachment :

Description :

Description : Shelter_housekeeping_Severity **Value** :

Attachment :

Description :

Description : Shelter_surroundings_cleaning **Value** :

Attachment :

Description :

Description : MDB_cables_connection_Severity **Value** :

Attachment :

Description :

Description : Ooredoo_Equipment_Availability **Value** :

Attachment :

Description :

Description : MDB_Main_Circuit_Breaker_status

Value : OK

Attachment :

Description :

Description : Access_Card_Availability_Remarks

Value : abc

Attachment :

Description :

Description : Grounding_Cables_labling_Remarks

Value :

Attachment :

Description :

Description : Access_Card_Availability_Severity

Value : Crtical

Attachment :

Description :

Description : Grounding_Cables_labling_Severity

Value :

Attachment :

Description :

Description : MDB_Main_Circuit_Breaker_Severity

Value :

Attachment :

Description :

Description : Shelter_indoor_inspection_Remarks

Value :

Attachment :

Description :

Description : Site_Power_configuration_pictures

Value :

Attachment :

Description :

Description : Grounding_Cables_tightened_Remarks **Value** :

Attachment :

Description :

Description : Main_Distribution_Board_MDB_Status **Value** : OK

Attachment :

Description :

Description : Shelter_indoor_inspection_pictures **Value** :

Attachment :

Description :

Description : Grounding_Cables_tightened_Severity **Value** :

Attachment :

Description :

Description : Main_Distribution_Board_MDB_Remarks **Value** :

Attachment :

Description :

Description : Shelter_outdoor_inspection_pictures **Value** :

Attachment :

Description :

Description : Main_Distribution_Board_MDB_Severity **Value** : Crtical

Attachment :

Description :

Description : Shelter_door_status_rubber_jack_etc_ **Value** :

Attachment :

Description :

Description : Pole_safety_climbing_or_Ladder_status **Value** :

Attachment :

Description :

Description	: Shelter_surroundings_cleaning_Remarks	Value	:
--------------------	---	--------------	---

Attachment :

Description :

Description	: Pole_foundation_status_cracked_paints_	Value	:
--------------------	--	--------------	---

Attachment :

Description :

Description	: Pole_safety_climbing_or_Ladder_remarks	Value	:
--------------------	--	--------------	---

Attachment :

Description :

Description	: Shelter_surroundings_cleaning_Severity	Value	:
--------------------	--	--------------	---

Attachment :

Description :

Description	: Pole_safety_climbing_or_Ladder_severity	Value	:
--------------------	---	--------------	---

Attachment :

Description :

Description	: Shelter_sealing_inspection_Hole_Testing_	Value	:
--------------------	--	--------------	---

Attachment :

Description :

Description	: Outdoor_or_Foundation_Inspection_pictures	Value	:
--------------------	---	--------------	---

Attachment :

Description :

Description : MDB_cables_connection_status_tight_connection_Value : OK

Attachment :

Description :

Description : Shelter_sealing_inspection_Hole_Testing_Remarks**Value** : abc

Attachment :

Description :

Description : Shelter_sealing_inspection_Hole_Testing_Severity**Value** :

Attachment :

Description :

Approval Date

Approval Remarks

Approved By