

SURVEY



Survey Number :	371	Date :	
-----------------	-----	--------	--

Survey General Information :

User	:	Assigned Date	:
Survey Template	:	Scheduled	:
Site	:	Due Date	:
Current Status	:	Arrived Date	:
	:	Closed Date	:

Survey Values

Description	:	Site_Type	Value	:	Rooftop
-------------	---	-----------	-------	---	---------

Attachment :

Description :

Description	:	Cable_Tray_	Value	:	OK
-------------	---	-------------	-------	---	----

Attachment :

Description :

Description	:	Access_Status	Value	:	OK
-------------	---	---------------	-------	---	----

Attachment :

Description :

Description	:	Lightning_rod	Value	:	OK
-------------	---	---------------	-------	---	----

Attachment :

Description :

Description	:	Busbar_Remarks	Value	:	
-------------	---	----------------	-------	---	--

Attachment :

Description :

Description	:	Busbar_Status_	Value	:	NOK
-------------	---	----------------	-------	---	-----

Attachment :

Description :

Description	:	Number_of_Gate	Value	:	
-------------	---	----------------	-------	---	--

Attachment :

Description :

Description : Busbar_Greased_ **Value** : OK

Attachment :

Description :

Description : Busbar_Severity **Value** :

Attachment :

Description :

Description : Lightning_cable **Value** :

Attachment :

Description :

Description : Site_Power_Type **Value** : kahramaa

Attachment :

Description :

Description : Tower_U_Clamps_ **Value** :

Attachment :

Description :

Description : COW_plate_number **Value** :

Attachment :

Description :

Description : Cable_Tray_Cover **Value** :

Attachment :

Description :

Description : Guy_Wires_Status **Value** :

Attachment :

Description :

Description : Generator_1_Brand **Value** :

Attachment :

Description :

Description : Generator_2_Brand

Value :

Attachment :

Description :

Description : Tower_Light_Brand

Value : Technovator

Attachment :

Description :

Description : Cable_Tray_remarks

Value :

Attachment :

Description :

Description : Number_of_padlock_

Value : 1

Attachment :

Description :

Description : Tower_Light_Status

Value : OK

Attachment :

Description :

Description : Cable_Tray_severity

Value :

Attachment :

Description :

Description : Number_of_Guy_Wires

Value : na

Attachment :

Description :

Description : Tower_Light_Remarks

Value :

Attachment :

Description :

Description : Tower_chairs_status **Value** :

Attachment :

Description :

Description : Cable_Tray_Grounding **Value** :

Attachment :

Description :

Description : Kahramaa_Meter_Owner **Value** :

Attachment :

Description :

Description : Site_Access_Pictures **Value** :

Attachment :

Description :

Description : Site_Access_pictures **Value** :

Attachment :

Description :

Description : Tower_Light_Severity **Value** :

Attachment :

Description :

Description : Tower_chairs_remarks **Value** :

Attachment :

Description :

Description : Vehicle_tires_status **Value** :

Attachment :

Description :

Description : Lightning_rod_Remarks **Value** :

Attachment :

Description :

Description : Tower_chairs_severityValue :

Attachment :

Description :

Description : Busbar_Greased_RemarksValue :

Attachment :

Description :

Description : Earth_Resistance_ValueValue :

Attachment :

Description :

Description : Fence_Grounding_StatusValue : OK

Attachment :

Description :

Description : Kahramaa_Meter_Number_ValueValue :

Attachment :

Description :

Description : Lightning_rod_SeverityValue :

Attachment :

Description :

Description : Tower_Grounding_StatusValue : OK

Attachment :

Description :

Description : Tower_U_Clamps_remarksValue :

Attachment :

Description :

Description : Access_procedure_Status **Value** : securitu access

Attachment :

Description :

Description : Busbar_Greased_Severity **Value** :

Attachment :

Description :

Description : COW_Inspection_pictures **Value** :

Attachment :

Description :

Description : Fence_Grounding_Remarks **Value** :

Attachment :

Description :

Description : Lightning_cable_Remarks **Value** :

Attachment :

Description :

Description : Tower_Grounding_Remarks **Value** :

Attachment :

Description :

Description : Tower_Light_Power_Input **Value** :

Attachment :

Description :

Description : Tower_U_Clamps_severity **Value** :

Attachment :

Description :

Description : Cable_Tray_Cover_remarks **Value** :

Attachment :

Description :

Description : Fence_Grounding_Severity

Value :

Attachment :

Description :

Description : Guy_Wires_Status_Remarks

Value :

Attachment :

Description :

Description : Lightning_cable_Severity

Value :

Attachment :

Description :

Description : Tower_Grounding_Severity

Value :

Attachment :

Description :

Description : Tower_foundation_remarks

Value :

Attachment :

Description :

Description : COW_verticality_deviation

Value :

Attachment :

Description :

Description : Cable_Tray_Cover_severity

Value :

Attachment :

Description :

Description : Canopy_foundation_remarks

Value :

Attachment :

Description :

Description : Grounding_Cables_labling_ **Value** : OK

Attachment :

Description :

Description : Guy_Wires_Status_Severity **Value** :

Attachment :

Description :

Description : Tower_foundation_severity **Value** :

Attachment :

Description :

Description : Canopy_foundation_severity **Value** :

Attachment :

Description :

Description : Earth_Pit_Grounding_Status **Value** : OK

Attachment :

Description :

Description : Fuel_Tank_Grounding_Status **Value** :

Attachment :

Description :

Description : Generator_Grounding_Status **Value** : NA

Attachment :

Description :

Description : Earth_Pit_Grounding_Remarks **Value** :

Attachment :

Description :

Description : Fuel_Tank_Grounding_Remarks **Value** :

Attachment :

Description :

Description	: Generator_Grounding_Remarks	Value	:
--------------------	-------------------------------	--------------	---

Attachment :

Description :

Description	: Grounding_Cables_tightened_	Value	: OK
--------------------	-------------------------------	--------------	------

Attachment :

Description :

Description	: Cable_Tray_Grounding_remarks	Value	:
--------------------	--------------------------------	--------------	---

Attachment :

Description :

Description	: Earth_Pit_Grounding_Severity	Value	:
--------------------	--------------------------------	--------------	---

Attachment :

Description :

Description	:	Fuel_Tank_Grounding_Severity	Value	:
--------------------	----------	------------------------------	--------------	----------

Attachment :

Description :

Description	: Generator_Grounding_Severity	Value	: Critical
--------------------	--------------------------------	--------------	------------

Attachment :

Description :

Description	: Cable_Tray_Grounding_severity	Value	:
--------------------	---------------------------------	--------------	---

Attachment :

Description :

Description	: Control_Panel_Photocell_Status	Value	: OK
--------------------	----------------------------------	--------------	------

Attachment :

Description :

Description : Control_Panel_Photocell_Remarks **Value** :

Attachment :

Description :

Description : Earth_Resistance_record_Coments **Value** : not possible

Attachment :

Description :

Description : Control_Panel_Photocell_Severity **Value** :

Attachment :

Description :

Description : Fence_concrete_foundation_status **Value** : OK

Attachment :

Description :

Description : Grounding_Cables_labling_Remarks **Value** :

Attachment :

Description :

Description : COW_verticality_deviation_remarks **Value** :

Attachment :

Description :

Description : Fence_concrete_foundation_remarks **Value** :

Attachment :

Description :

Description : Gate_not_damaged_or_broken_status **Value** : OK

Attachment :

Description :

Description : Grounding_Cables_labling_Severity **Value** :

Attachment :

Description :

Description : Site_Power_configuration_pictures

Value : https://qtrtest.cmrisoftware.com//Attachments\EtSurvey/275\23_07_2020_09_43_249722.jpg,

Attachment :

Description :

Description : COW_verticality_deviation_severity

Value :

Attachment :

Description :

Description : Fence_concrete_foundation_severity

Value :

Attachment :

Description :

Description : Gate_not_damaged_or_broken_remarks

Value :

Attachment :

Description :

Description : Grounding_Cables_tightened_Remarks

Value :

Attachment :

Description :

Description : Fence_has_no_cuts_or_damages_status

Value : OK

Attachment :

Description :

Description : Gate_not_damaged_or_broken_severity

Value :

Attachment :

Description :

Description : Grounding_Cables_tightened_Severity

Value :

Attachment :

Description :

Description : Fence_has_no_cuts_or_damages_remarks **Value** :

Attachment :

Description :

Description : Vehicle_overall_status_broken_items_ **Value** :

Attachment :

Description :

Description : Earth_pits_status_cover_connectivity_ **Value** : OK

Attachment :

Description :

Description : Fence_has_no_cuts_or_damages_severity **Value** :

Attachment :

Description :

Description : Generator_concrete_foundation_remarks **Value** :

Attachment :

Description :

Description : Earth_pits_remarks_cover_connectivity_ **Value** :

Attachment :

Description :

Description : Generator_concrete_foundation_severity **Value** :

Attachment :

Description :

Description : Tower_safety_climbing_or_Ladder_status **Value** : OK

Attachment :

Description :

Description : Earth_pits_severity_cover_connectivity_ **Value** :

Attachment :

Description :

Description : Tower_foundation_status_cracked_paints_

Value : OK

Attachment :

Description :

Description : Tower_safety_climbing_or_Ladder_remarks

Value :

Attachment :

Description :

Description : Tower_safety_climbing_or_Ladder_severity

Value :

Attachment :

Description :

Description : Outdoor_or_Foundation_Inspection_pictures

Value :

Attachment :

Description :

Description : Tower_Light_Photo_Cell_and_Grounding_Pictures

Value :

Attachment :

Description :

Description : Generator_concrete_foundation_no_cracks_status

Value : NA

Attachment :

Description :

Description : Tower_paint_is_fine_scratch_and_rust_free_status

Value :

Attachment :

Description :

Description : Tower_paint_is_fine_scratch_and_rust_free_remarks

Value :

Attachment :

Description :

Description : Canopy_foundation_cracked_paints_nuts_bolts_status **Value** : OK

Attachment :

Description :

Description : Tower_paint_is_fine_scratch_and_rust_free_severity **Value** :

Attachment :

Description :

Description : Tower_joint_bolts_use_torque_wrench_semi_annual_status **Value** :

Attachment :

Description :

Description : Tower_joint_bolts_use_torque_wrench_semi_annual_remarks **Value** :

Attachment :

Description :

Description : Tower_joint_bolts_use_torque_wrench_semi_annual_severity **Value** :

Attachment :

Description :

Approval Date **Approval Remarks** **Approved By**