

WORK ORDER REPORT



Work Order Number :	7	Date :	June 30, 2019 03:50 PM
---------------------	---	--------	------------------------

Work Order General Information :

Department	: H&S	Date of Creation	: June 30, 2019 03:50 PM
Sub Department	: H&S	Scheduled	: June 30, 2019 03:49 PM
Description	: H&S site audit - PM	Started Date	: June 30, 2019 03:52 PM
Instruction	: Check for all H&S requirement on site	Closed Date	: June 30, 2019 05:52 PM
Current Status	: Completed		

Physical Site Detail :

Site Coordinates	25.1752410000	Latitude	Site Code	Site1303
	51.3850010000	Longitude	Site Category	2

Work Order Task Summary :

Instruction	:	Complete Status	:
Response Selection	:	Completed by	:
Version	:	Completed at	:
Task Status	:	Task Comment	:

Assigned User Detail:

Name	: Alisha Varkey	Mobile Primary	:
Designation	: AC Team Leader	Mobile Secondary	:
Name	: MOHAMMED RAHEEZ	Mobile Primary	:
Designation	: EHS Supervisor	Mobile Secondary	:

Work Order Notes:

Work Order Note	Note Date	User Name
Workorder Status Changed to Completed by Alisha Varkey	July 08, 2019 09:45 AM	Alisha Varkey
Workorder Updated by Alisha Varkey on 2019-07-08 09:45:12	July 08, 2019 09:45 AM	Alisha Varkey
Workorder Updated by Alisha Varkey on 2019-07-07 10:54:03	July 07, 2019 10:54 AM	Alisha Varkey
Workorder Updated by Alisha Varkey on 2019-07-01 09:48:03	July 01, 2019 09:48 AM	Alisha Varkey
Workorder Status Changed to InProgress by MOHAMMED RAHEEZ	June 30, 2019 03:53 PM	MOHAMMED RAHEEZ
Workorder Status Changed to Arrived by MOHAMMED RAHEEZ	June 30, 2019 03:53 PM	MOHAMMED RAHEEZ
Workorder Status Changed to InTransit by MOHAMMED RAHEEZ	June 30, 2019 03:53 PM	MOHAMMED RAHEEZ
Workorder Status Changed to Confirmed by MOHAMMED RAHEEZ	June 30, 2019 03:52 PM	MOHAMMED RAHEEZ
Workorder Updated by Babatunde Jolaoye on 2019-06-30 15:51:54	June 30, 2019 03:51 PM	Babatunde Jolaoye
Workorder Assigned To (132)	June 30, 2019 03:50 PM	Babatunde Jolaoye
Status set to Assigned	June 30, 2019 03:50 PM	Babatunde Jolaoye
Workorder Created Without Template	June 30, 2019 03:50 PM	Babatunde Jolaoye

Asset :

Asset Name	: Harmer & simmons	IMM Description	:
Manufacturer	: Harmer & simmons	IMM Model Number	: 8KW
Barcode	: A0000004	IMM Part Number	: 123456

Survey :

Survey Name	: System.Data.DataRowView
-------------	---------------------------

STC :

Asset Name	:	IMM Description	:
Manufacturer	:	IMM Model Number	:
Barcode	:	IMM Part Number	:

Attachment :

Description :

Description :

Description :

Description :